

	H (vyska horni casti steny)	beta	a	b	c	h (vyska pasu steny)	alfa	NP	fi,ef	gama	ny	c,ef	delta	f	beton	mi
1	4	10	0.4	0.45	1.65	1.2	0	1-K1	25	18		18	10	50	C30/37	0.5
2	5	5	0.5	0.3	1.8	1	0	1-K2	20	19		19	8	20	C20/25	0.6
3	6	-10	0.6	0.4	2.2	1.2	0	2	30	18.5		15	10	10	C30/37	0.65
4	5	10	0.5	0.35	1.85	1	0	3	27	19.5		30	10	40	C20/25	0.5
5	5	10	0.5	0.4	1.9	1.2	0	1-K1	25	18		20	10	30	C30/37	0.6
6	5.5	10	0.55	0.6	2.25	1.2	0	1-K2	20	19		18	8	40	C20/25	0.65
7	5	-10	0.5	0.3	1.8	1	0	2	30	18.5		19	10	70	C30/37	0.5
8	8	-10	0.8	0.55	2.95	1.2	0	3	27	19.5		15	10	60	C20/25	0.6
9	8	-10	0.8	0.5	2.9	1	0	1-K1	25	18		30	10	50	C30/37	0.65
10	6.5	-5	0.65	0.5	2.45	1.4	0	1-K2	25	19		20	10	30	C20/25	0.5
11	7.5	-10	0.75	0.45	2.7	1	0	2	20	18.5		18	8	20	C30/37	0.6
12	6.5	-5	0.65	0.45	2.4	1.2	0	3	25	19.5		19	10	25	C20/25	0.65
13	5	-5	0.5	0.35	1.85	1	0	1-K1	20	18		15	8	15	C30/37	0.5
14	4	-5	0.4	0.3	1.5	1	0	1-K2	30	19		30	10	37	C20/25	0.6
15	6	-5	0.6	0.45	2.25	1	0	2	27	18.5		20	10	10	C30/37	0.65
16	5	-5	0.5	0.4	1.9	1.2	0	3	20	19.5		18	10	18	C20/25	0.5
17	9	-10	0.9	0.75	3.45	1.2	0	1-K1	25	18		18	10	30	C30/37	0.6
18	5.5	10	0.55	0.55	2.2	1	0	1-K2	20	19		19	8	40	C20/25	0.65
19	4.5	0	0.45	0.4	1.75	1.2	0	2	30	18.5		15	10	70	C30/37	0.5
20	5.5	-5	0.55	0.5	2.15	1.2	0	3	27	19.5		30	10	60	C20/25	0.6
21	6	10	0.6	0.55	2.35	1	0	1-K1	25	18		20	10	50	C30/37	0.65
22	6	10	0.6	0.6	2.4	1.2	0	1-K2	20	19		18	8	30	C20/25	0.5
23	8.5	-10	0.85	0.6	3.15	1	0	2	30	18.5		19	10	20	C30/37	0.6
24	6	-5	0.6	0.5	2.3	1.2	0	3	27	19.5		15	10	30	C20/25	0.65
25	4.5	10	0.45	0.5	1.85	1	0	1-K1	25	18		30	10	40	C30/37	0.5
26	6.5	-10	0.65	0.4	2.35	1.2	0	1-K2	20	19		20	8	70	C20/25	0.6
27	4.5	0	0.45	0.35	1.7	1	0	2	30	18.5		18	10	60	C30/37	0.65
28	5	5	0.5	0.5	2	1.2	0	3	27	19.5		18	10	50	C20/25	0.5
29	5.5	-5	0.55	0.45	2.1	1	0	1-K1	25	18		19	10	30	C30/37	0.6
30	4.5	10	0.45	0.45	1.8	1.2	0	1-K2	20	19		15	8	20	C20/25	0.65
31	7	-5	0.7	0.4	2.5	1	0	2	30	18.5		30	10	25	C30/37	0.5
32	7	-5	0.7	0.6	2.7	1.2	0	3	27	19.5		20	10	15	C20/25	0.6
33	4	0	0.4	0.35	1.55	1	0	1-K1	25	18		18	10	37	C30/37	0.65
34	5.5	-10	0.55	0.4	2.05	1	0	1-K2	20	19		19	8	10	C20/25	0.5
35	4	10	0.4	0.5	1.7	1	0	2	30	18.5		15	10	18	C30/37	0.6
36	7	-10	0.7	0.55	2.65	1	0	3	27	19.5		30	10	30	C20/25	0.65
37	8.5	-10	0.85	0.65	3.2	1.2	0	1-K1	25	18		20	10	40	C30/37	0.5
38	7.5	-10	0.75	0.5	2.75	1.2	0	1-K2	25	19		18	10	70	C20/25	0.6
39	9	-10	0.9	0.7	3.4	1	0	2	25	18.5		19	10	60	C30/37	0.65
40	5	-5	0.5	0.45	1.95	1.2	0	3	20	19.5		15	8	20	C20/25	0.5
41	4.5	-5	0.45	0.3	1.65	1	0	1-K1	30	18		30	10	30	C30/37	0.6
42	4	0	0.4	0.4	1.6	1.2	0		27	19		15	10	20	C20/25	0.65